

Map ID
Direction
Distance
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

DV607
East
1/2-1
0.904 mi.
4774 ft.

VAULT 4886
BRIGHTON 7TH ST/NEPTUNE
BROOKLYN, NY

NY Spills S106013768
N/A

Site 2 of 2 in cluster DV

Relative:
Higher

Actual:
9 ft.

SPILLS:

Name: VAULT 4886
Address: BRIGHTON 7TH ST/NEPTUNE
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 0301291 / 2003-06-17
Facility ID: 0301291
Facility Type: ER
DER Facility ID: 219647
Site ID: 269704
DEC Region: 2
Spill Cause: Unknown
Spill Class: D3
SWIS: 2401
Spill Date: 2003-05-05
Investigator: AERODRIG
Referred To: Not reported
Reported to Dept: 2003-05-06
CID: 398
Water Affected: Not reported
Spill Source: Unknown
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2003-05-06
Spill Record Last Update: 2003-06-17
Spiller Name: Not reported
Spiller Company: UNKNOWN
Spiller Address: Not reported
Spiller Company: 001
Contact Name: PAUL DIDONATO
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was
RODRIGUEZ E2MIS 148228 5-5-03 1105 HRS A. BOVE # 14120 SPLICER

Remarks:

NETWORK REPORTS WHILE MAKING ROUTINE INSPECTION (FOR FLUSH DEPT) IN
VS4886 (FDR.7B41) E/S NEPTUNE AVE 40' N/O BRI. 7 ST HE FOUND APPROX
5 GALLONS UNKNOWN OIL ON 75 GALLONS WATER. HE INSPECTED TRANSF OIL
LEVEL , IT IS GOOD AND HE PRESSURE TESTED UNIT AND IT HELD PRESSURE.
HISTORICAL RECORD OF TRANSF IS 9 PPM AND WAS LAST TESTED 5-24-90 .
LIQUID SEEEMS CONTAINED. HE TOOK A LIQUID SAMPLE FROM STRUCTURE AND
REQUESTED EMERG PRIORITY FOR PCB SAMPLE RESULTS. CLEANUP PENDING
SAMPLE RESULTS. CHAIN OF CUSTODY # CC16026. HE PLACED E.S.TAG # 36404
5/5/03=1800hrs Oil Identification Analysis by NYSDOH 310-13
(Hydrocarbon Scan) Insufficient amount of sample extracted to perform
oil identification. Monday, May 05, 2003 8:14 PM Lab Sequence Number:
03-03663-001 PCBs <1ppm Flash Point, PMCC > 140 deg F D93-00/EPA 1010
UPDATE - 06-MAY-2003 12:28 HRS. ENVIR. FLUSH DEPT. MECH-A REPORTS:
STRUCTURE DBL. WASHED WITH BIO-GEN 760, ENVIR. TAG# 36404 REMOVED.
SUMP FOUND SEALED IN STRUCTURE. CLEANUP COMPLETE. 100 "
"CON EDISON 148228. SPILL ON 75 GALS OF WATER. CLEAN UP WILL START
AFTER VEHICLE REMOVED FROM OVER MANHOLE."

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

All Materials:

Site ID:	269704
Operable Unit ID:	867685
Operable Unit:	01
Material ID:	505786
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	5.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported